

XP 56 MOTORS WIRING DIAGRAM

SINGLE-PHASE DUAL VOLTAGE

